



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

Supervisor 007

### Inspection Report Minerals Regulatory Program

Report Date: June 27, 2005

**Mine Name:** Windy #3

**Operator or Permittee Name:**

Color County Rock

**Inspector(s):** Doug Jensen

**Permit number:** S/053/071

**Inspection Date:** June 21, 2005

**Inspection Start Time:** 5:45 PM

**Inspection End Time:** 6:15 PM

**Other Participants:** None

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Checked the site while I was in the area.

**Directions to the site:**

See Previous inspection memos.

**Inspection Summary:**

There has been some activity at the site since my last visit. Some large rocks have been moved down the hill to an area near the Motoqua road.



Inspection Date: June 21, 2005; Report Date: June 27, 2005  
Page 2 of 2  
S/053/071


There was no activity at the time of my visit. There has not been any mining at the site for some time as judging by the amount of sweet clover growing over the site. The sweet clover must have been the result of the BLM seeding of a fire which occurred several years ago.

The site was stable with no concerns that were evident. Photos were taken and are included in this report.

**GPS Data:**

This site will need to be GPS'd on my next visit, to document the total disturbance at the site.

**Inspector's Signature**

A handwritten signature in dark ink, appearing to read "Doug Larson", written over a horizontal line.

**Date:** June 27, 2005

DJ:jb

Enclosures: photos

cc: Color Country Rock, Operator  
Rody Cox, BLM, St George FO

O:\M053-Washington\s0530071-Windy\Draft\06212005insp.doc







